

FIG. 3

FIG. 2AFIG. 2BFIG. 2

Select Primary Site Select Other Site 回台 Submittals 一一 1 (Latest) 中台 Maintenance 031 - Home Laundry AP 1 (AP1)  $\overline{\nabla}$ Add Other Site Delete Site --○ Initial Request --○ Supplier Reply Dwg. No: Rev.\*: 0 PT/0p.\*: Rev.\*: 0 中台 Measurement Part Name: 百合 Supplier Sub System: -- Dimension Manufacturing Contacts -- Appearance Authority Name\* Title\* -- Lab Initiator\* Just Glenn A(LC26367) AQ Eng --○ Dimension Site Coordinator\* ▽ Proj Coord  $\nabla$ -→ Appearance Dispositioner Find Design Eng  $\nabla$ --○ Lab Approver Find AQ Eng O Remarks Quality Engineer Find AQ Eng └-○ Disposition Documents
Charge History Find Add Contacts Delete Contacts Internal Mfg: \*\*Select one of the Two Supplier Code: Supplier Type  $\overline{\nabla}$ Supplier Name Street Address1\* Street Address2\* City/State/Country/Zip\* Supplier POC\* User No\* Bus Phone\* E-mail Address\* Related Suppliers Supplier Code/Name Authority Туре Find Add Supplier Delete Supplier Parts Reg For: No. of Samples: Dimension\* O Yes No
 0 O Yes Laboratory\* ● No 0 O Yes 0 Appearance\* No
 O Yes Toxicity No

<u>~200</u>

FIG. 2A

+

Tooling No.							}		
Cavity							]		
First Piece Type*		● Tooling	, ,	O Pro	ducto	r	]		
Reason for FPR*			-			∀	1		
Due Date (MM/DD/Y	Y)*						ĺ		
Send Samples TO*							j		
Project No.							1		
Purchase Order No.	,					-	ว์		
**Select one of the	Two BCR						BCN	She	et No.
Сара	bility Study,Gag	e R&R requ	irem	ents –	ADD	requi	red dim	ensi	ons
Сар	Study,Gage R&I	₹		Dimen	nsion	Sh	eet		Zone
						0			
	Add Docur	nents		D	elete	Docu	ments		
	Required v	vith first Pi							
Fpr Samples*			O Y	'es	•	No			
Process Flow/Map*			O Y	'es	◉	No	0	On	File
Quality Plan*			O Y	'es	•	No	0	On	File
Required for CTQ	Capability Stu	dies*	O Y	es es	•	No	0	On	File
	Gage R&R*	$\overline{}$	O Y		⊚	M-	$\sim$	<u></u>	File

FIG. 2B

+





FIG. 4


+

				-500					5/8
☐ Main - GE Appliance	s Cai	mco & Mo	abe						
502	502 Electronic First Piece System								Help
Worklist Search Create	Site Coordinator Offline								
Transfer Request	Expor	t Print Cl	lick On 'Fpr/Sut	omittal' Val	ue to Open	a Specific	First Pie	ce Re	eport
Worklist of		Fpr/Submit	Base Dwg/Rev	Parts/Rev	Part Desc	Tool/Cavity	Supplier	Site	Status
Jane Doe Find	Сору		1895-78/0	526A/0	WIDGET		GEA	031	Initiated
Refresh	Сору	310100003/1	4569-789/1	52/1	HOSE		GEA	031	Initiated
Initiated(5)	Сору	410100004/1	/0	/0				041	Initiated
	Сору	410100005/1	/0	/0				041	Initiated
Posted To Supplier(1)	Сору	F10100001/1	/0	/0				0F1	Initiated
Acknowledged By Supplier(1)									
			◁						$\triangleright$
504 FIG. 5									

				<del>600</del>					
☐ Main — GE Appliance	s Car	nco & M	labe						
		Electro	onic First Pi	ece Syste	m			[	Help
Worklist Search Create	Site	Coordina	tor Offline	,					
Transfer Request	Expor	t Print (	Click On 'Fpr/S	ubmittal' Val	ue to Open	a Specific	First Pie	ce R	eport
Worklist of		Fpr/Submit	t Base Dwg/Re	v Parts/Rev	Part Desc	Tool/Cavity	Supplier	Site	Status
Jane Doe Find	Сору	410100003/1	/0	/0				041	Initiated
Refresh	Сору	419100004/1	/0	/0				041	Initiated
Initiated(4)	Сору	410100005/1	/0	/0				041	Initiated
	Сору	F10100001/1	70	/0				OF1	Initiated
				by copying		create a D ng similar R s).		port	Δ
			<b>6</b> 02	<del>-</del>					

FIG. 6





	900	//8
☐ Main — GE Appliances	Camco & Mabe	
	Electronic First Piece Online	
FPR No/Submittal No: 4101000	Save Changes   Cancel Changes   Save C	Offline Print
Status: Posted To Supplier Logged in As: Initiator, Site Coo		
Acknowledged Cancel	Request	
	Downston for the CDD	
〇 貝合 Submittals	Remarks for the FPR	4
└ -○ 1 (Latest)   中令 Maintenance	Exemplary Remark Entered On	Entered By
r → Initial Request - Supplier Reply		
中令 Measurement   中令 Supplier	Dimensions for cavity 1, 2, 3, only will 02/02/01 submit cav. 4 dimensions after reworked.	L505271
☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐		İ
	Supplier's Remark	
O Dimension O Appearance O Lab	)/	
O Remarks O Disposition		
Documents Charge History		
	902	FIG. 9
	1000	*
☐ Main — GE Appliance	s Camco & Mabe	
	Electronic First Piece Online	
FPR No/Submittal No: 4101000 Status: Initiated	Save Changes   Cancel Changes   Save	Offline Print
Logged in As: Initiator		
Post To Supplier Can	cel Request 1002	
<b>A</b>	First Piece Report Status	
会 Submittals 「こっ1 (Latest) 中令 Maintenance	Dimension     Dimension   Dime	
	Laboratory □ □ Appearance □ □	
├-○ Supplier Reply ├-○ Measurement		chauld complete
	code, for example. before sendi	should complete ng to approver.
O Appearance	(Use drop-	-down boxes.)
占合 Mfg. ○ Dimension	Part Used On	
O Appearance O Lab I O Remarks		<del></del>
L-O Disposition	EL/Dev# Program Name # of Parts Program Desc	
-O Charge History	Sub Component	




FIG. 11

